

## Attachment C

Summary of Distribution Circuit Field Inspection by ICC Staff			
<b>Utility:</b>	<b>CILCO</b>	<b>Date:</b>	<b>8/29/01</b>
<b>Circuit:</b>	<b>Stark 182-002 (Wyoming)</b>	<b>Inspector:</b>	<b>J. D. Spencer, G. E. Rochrohr</b>
<b>Gen. Notes:</b> Very few of the roads were labeled on the maps, making the maps difficult to follow. Most of the downguys throughout the circuit did not have guy markers. Lightning arresters have been added at several locations throughout the circuit.			
<i>Map No.</i>	<i>Item Description</i>	<i>Photo(s)</i>	<i>Location</i>
1 of 35	Split arm & steel pin through arm (UB on 69kV line)	R19	Unlabeled 900E north of W. County Line Rd.
1	Split pole top & part of pole missing		Unlabeled 1000E south of CH 4 (north of Sta.
2	Primary through soft maple trees		Near Stas. 502602, 502610, & 550011 (streets not labeled--NW corner of map)
2	Row of soft maple trees into primary (with burning)	R18	Both sides of Sta. 502612 (streets not labeled--NW corner of map)
3	Maple trees close to primary		South of Sta. 505586 near NW corner of map (streets not labeled)
5	Trees close to primary		West of tap to Sta. 506819 on E-W road (not labeled)
5	Pole top damaged (wood missing)		East of Sta. 551201 on E-W road (road not labeled)
5	Split pole top & woodpecker holes in pole		East of Sta. 551201 on E-W road (road not labeled)
7	Split pole top		On 830E north of 200N (roads not labeled on map)
7	Broken downguy		On 830E north of 200N (roads not labeled on map)
7	Downguy damaged (hit by vehicle)		On E-W road west of tap to Sta. 505349 (roads not labeled on map)
8	2 shell rotted poles		At Sta. 551199 and just south of there on N-S road (road not labeled on map)
8	Pole top damaged		CH 3 west of 555084
8	Split pole top		On unlabeled N-S road south of CH 3 (south of 555084)
8	Old lightning damage to pole		On unlabeled N-S road south of CH 3 (south of 555084)
8	Bottom bolt coming out of pole top pin		On unlabeled N-S road south of CH 3 (south of 555084)
8	Missing downguy		Sta. 507348 on unlabeled N-S road (1200E)
8	Trees close to primary		Between Stas. 510913 & 502652 on CH 3

## Attachment C

<i>Map No.</i>	<i>Item Description</i>	<i>Photo(s)</i>	<i>Location</i>
9	Broken brace		On 1300E north of Sta. 506559
9	Shell rotted pole		On 1300E between Stas. 551205 & 502659
9	Soft maples close to primary		On 1300E north of Sta. 551210
9	3 shell rotted poles		On unlabeled N-S road (1400E) between Sta. 505582 and unlabeled E-W road to the north
9	2 split pole tops		On unlabeled N-S road (1400E) north of fused cutout 555090
11	Lightning damage to several poles (& photo of split pole top)	R16	Along E-W road at NW corner of map and on 815E to the south (roads not labeled on map)
11	Primary with excessive sag		815E north of 345N (roads not labeled on map)
11	Bottom of pole splintered		Just west of 950E (not labeled on map) in line feeding Sta. 507219
11	Primary contacting cedar tree		East of 950E (not labeled on map) along E-W road (not labeled)
11	Woodpecker holes in pole		East of 950E (not labeled on map) along E-W road (not labeled)
11	Broken downguy		In line south and east from tap to Sta. 507217 along road not labeled (1020E) on east side of map
11	Woodpecker holes in 2 poles		On 300N (not labeled) at 950E (not labeled) and east of Sta. 507220
11	Trees close to primary		On 300N (not labeled) east of Sta. 507220
12	2 split pole tops		Along CH 7 (300N) east of tap to Sta. 551196 and east of creek
12	Woodpecker hole (nest) in pole & pin bolts coming out	R17	Along CH 7 (300N), 2nd pole west of creek
12	Lightning damaged pole top		Along CH 7 (300N), 3rd pole west of State Hwy. 91 (1200E)
12	Primary pin bolt coming out		Along State Hwy. 91 north of tap to Sta. 506928
13	Lightning splintered pole top & woodpecker hole in pole	R15	Along 300N just east of 1300E (roads not labeled on map)
13	Woodpecker holes in pole		1st pole west of Sta. 505684 on 300N (road not labeled on map)

## Attachment C

<i>Map No.</i>	<i>Item Description</i>	<i>Photo(s)</i>	<i>Location</i>
13	Split pole top	R14	Along 300N, east of Sta. 505684 (road not labeled on map)
13	2 shell rotted poles (some splintering)		Along 1400E, north of 300N (roads not labeled on map)
13	Badly shell rotted pole (has yellow ribbon)	R13	Along 300N, just east of 1400E (roads not labeled on map)
14	Lightning damaged pole	R12	CH 13 at 1600E (not labeled on map)
14	Broken brace, split arm, & split pole top (lightning damage)	R11	400N, 1st pole east of 1600E (roads not labeled on map)
14	Split pole top		CH 13 (400N) east of 556445
16	Split pole top		450N (not labeled on map) east of Sta. 505942
17 (1 of 2)	Tree close to primary (notched)		On E-W road (not labeled), just east of tap to Sta. 506266 (near SW corner of map)
17 (1 of 2)	Neutral pin through arm		State Hwy. 91 south of Sta. 551193
19	Shell rotted pole (at top)		At Sta. 551120 on 1500E (not labeled on map)
19	Woodpecker hole in pole below neutral		North of Sta. 551106 on 1600E (not labeled on map)